


AIXIA

MODELO 815 LIJADORA ORBITAL 74X145MM



PART LIST

No.	Parts No.	Description	Q't	No.	Parts No.	Description	Q't
1	7100-01	Valve Lever	1	40	7100-40	O-Rin P6	1
2	7100-02	S rin Pin 3x25	1	41-1	7100-41-1	Silencer	1
3	7100-03	Bod Cover	1	41-2	7100-41-2	E ector Dust Free	1
4	7100-04	Conical Washer M3	2	42	7100-42	Screw M5x10	4
5	7100-05	Screw M3x8	2	43	7100-43	Su ort	4
6	7100-06	Bod	1	45	7100-45	Bearin 62002RS	1
7	7100-07	Re ulator	1	46	7100-46	Shoe	1
8	7100-08	O-Rin P5	2	47	7100-47	Screw M4x6	6
10	7100-10	Retainin Rin E7	2	48	7100-48	Cli Set	2
11	7100-11	Re ulator Lever	1	49	7100-49	5 Washer	1
12	7100-12	Screw M4x6	1	50	7100-50	Ca Screw M5x10	1
13	7100-13	Valve Pin Incl. 14	1	51-1	7100-51-1	Non-Vacuum Pad Stick t e	1
14	7100-14	O-Rin Incl. 13	1	51-2	7100-51-2	Non-Vacuum Pad Velcro t e	
15	7100-15	Valve S rin	1	51-3	7100-51-3	Vacuum Pad Stick t e	
16	7100-16	O-Rin P8	1	51-4	7100-51-4	Vacuum Pad Velcor t e	
17	7100-17	Valve Ca	1	52	7100-52	Screw M4x6	4
18	7100-18	PS-Ada ter	1	53-1	7100-53-1	Screw M5x8	4
19	7100-19	Screw M6x10	1	59	7100-59	C linder Set	1
20	7100-20	Conical Washer M6	1	59-1	7100-59-1	C linder	1
21	7100-21	Bearin 6000ZZ	1	59-2	7100-59-2	O-Rin P7	1
22	7100-22	U-Bearin Case	1	59-3	7100-59-3	S rin Pin 3x5	1
23	7100-23	U-Side Plate	1	59-4	7100-59-4	S rin Pin 3x5	1
27	7100-27	L-Side Plate	1	59-5	7100-59-5	S rin Pin 3x5	1
29	7100-29	Bearin 6000ZZ	1	60	7100-60	Dust Hose Set Dust Free	1
31	7100-31	H/R Ke 3x13	1	61	7100-61	L-Bearin Case	1
32	7100-32	L-Balancer	1	62	7100-62	Rotor Shaf	1
33	7100-33	Ca Screw M5x15	1	63	7100-63	S c-Bearin Case	1
35	7100-35	Felt Rin	1	64	7100-64	Felt Rin 22	1
36	7100-36	Bod Packin	1	65	7100-65	Dust Ba	1
37	7100-37	Base Plate	1	66	7100-66	Rotor	1
38	7100-38	Ca Screw M4x15	4	67	7100-67	Vane	5
39	7100-39	Screw M4x8	1	68	7100-68	Lock Washer	1

ST-7100-P-0611B-KM

AIRALDE

Pol. Ind. Eitua nº52 Pab.5A - 48240 Berriz (Bizkaia)
Telf.:946 236 010 | Fax.:946 236 011 | airtalde@airtalde.es | www.airtalde.es